



Photographs I and J. On-site dilapidated barn and existing well tank in southeastern parcel.



Photographs K and L. On-site barns associated with equestrian center in southeastern parcel.

On-site Visual Elements

VALIANO

Figure 16e



Photograph A. View looking southwest from Hill Valley Drive.



Photograph B. View looking southwest from Country Club Drive.

I:\PROJECTS\UPO\UPO-08_Valiano\Map\EN\Visual\Fig17a_OffsiteVantagePoints.mxd IPQ-11 09/05/13 -RK

Off-site Vantage Points

VALIANO

Figure 17a



Photograph E. View looking west from Live Oak Road, obstructed view of site.



Photograph F. View looking west from Oak Canyon Place, obstructed view of site.


E:\PROJECTS\11\1101\1101_08_Valiano\Map\EN\Visual\Fig17c_OffSiteVantagePoints.mxd IPQ-11 09/05/13 - RK

Off-site Vantage Points

VALIANO

Figure 17c

-  Project Boundary
-  3 Miles from Project Site
-  Areas with Views of Project Site



E:\PROJECTS\I\PO\I\PO-08_Valiano\Map\ENV\Visual\Fig18_Viewshed.mxd IPO-11 04/29/14-RK

Project Viewshed Map

VALIANO

Figure 18

I:\PROJECTS\1100\1100-08_Valiano\Map\ENV\Visual\Fig 19a_19a_Existing Views.snd 11/25/14 -RK



Key View 1 - Looking west from Country Club Drive toward northern portion of Project site (Neighborhood 4)



Key View 2 - Looking southwest from Country Club Drive toward southeastern corner of Project site (Neighborhood 5)

I:\PROJECTS\1100\1100-08_Valiano\Map\ENV\Visual\Fig_19a_19d_Existing_Visual.mxd



Key View 3 - Looking northwest from Country Club Drive toward southeastern corner of Project site (Neighborhood 5)

I:\PROJECTS\11\1101\08_Valiano\Map\ENV\Visual\Fig 19a-19d_Existing Views.indd



Key View 4 - Looking northeast from Seeforever Drive toward northern portion of Project site (Neighborhoods 2, 3, and 4)

I:\PROJECTS\IPQ\IPQ-08_ValianoMap\ENV\Visual\Fig 19a-19d_Existing Views.mxd