

APPENDIX B

Site Photographs



Photograph B1. Survey Area overview, northwest corner of Survey Area, facing southeast.



Photograph B2. Survey Area overview, northeast corner of Survey Area, facing northeast.



Photograph B3. Survey Area overview, central portion of Survey Area north of Jewel Valley Road, facing south.



Photograph B4. Survey Area overview, central portion of Survey Area north of Jewel Valley Road, facing northwest.



Photograph B5. Overview of relict basin (FP04) cut from hydrologic input and output, facing west-northwest.



Photograph B6. Survey Area overview, south of Jewel Valley Road atop FP04, facing southwest.



Photograph B7. Survey Area overview, facing downslope/north.



Photograph B8. Survey Area overview at approximate center-west of the Survey Area, facing north.



Photograph B9. Elevated culvert facilitating flow across railroad in yellow circle, facing south.



Photograph B10. Elevated culvert facilitating flow across railroad in yellow circle, facing southeast.



Photograph B11. Survey Area overview, facing north–northwest. Southwestern portion of the Survey Area. No aquatic resources observed.



Photograph B12. Survey Area overview, south–central portion of the Survey Area, facing north.



Photograph B13. Survey Area overview, southeastern portion of the Survey Area, facing east.



Photograph B14. Survey Area overview, southeastern portion of the Survey Area, facing northwest.



Photograph B15. Survey Area overview, southeastern portion of the Survey Area, facing south.



Photograph B16. Survey Area overview, southeastern portion of the Survey Area, facing south.



Photograph B17. Berm separating S65 and S66. Dirt access road visible in foreground. View facing northeast.



Photograph B18. Berm separating features S65 and S66. Foreground correlates with NWI-mapped freshwater pond; however, no hydrology indicators were observed. View facing southwest.



Photograph B19. Feature S03, view facing downstream/east.



Photograph B20. Feature S04, view facing downstream/east.



Photograph B21. Feature S06, view facing downstream/southeast.



Photograph B22. Feature S08, view facing upstream/west-southwest.



Photograph B23. Feature S09, view facing upstream/southeast.



Photograph B24. Feature S15, view facing downstream/south.



Photograph B25. Feature S18, view facing upstream/east-northeast.



Photograph B26. Feature S23, view facing downstream/southwest.



Photograph B27. Feature S27, view facing upstream/southwest.



Photograph B28. Feature S29, view facing downstream/southeast.



Photograph B29. Feature S33, view facing downstream/southeast.



Photograph B30. Feature S33, view facing downstream/northeast.



Photograph B31. Feature S35, view facing downstream/southeast.



Photograph B32. Feature S38, view facing downstream/east-northeast.



Photograph B33. Feature S38, view facing downstream/northeast.



Photograph B34. Feature S40, view facing downstream/north.



Photograph B35. Feature S45, view facing upstream/southwest.



Photograph B36. Start of feature S47 from roadside erosional gully, view facing downstream/west.



Photograph B37. Feature S48, view facing downstream/southeast.



Photograph B38. Feature S51, view facing downstream from access road/southeast.



Photograph B39. Feature S45 crossing access road. Short-lived erosional gully in background. View facing upslope/north.



Photograph B40. Confluence at feature S47, view facing upstream/northwest.



Photograph B41. Feature S53, from terminus of feature where it dissipates as sheet flow. View facing upstream/north.



Photograph B42. Feature S56, view facing upstream at sheet flow terminus of feature/west-southwest.



Photograph B43. Start of feature S60 from flow conveyed by road. Riprap is in place to reduce scour at side of the road. View facing downstream/southwest.



Photograph B44. Feature S62, view facing upstream/north–northwest. Poor drainage definition obscured by previous seasons' mustards.



Photograph B45. Feature S64, view facing downstream/east.



Photograph B46. Start of feature S56. Overview facing southeast, perpendicular to the direction of flow.



Photograph B47. Feature S66 overview, facing upstream/northwest.



Photograph B48. Feature S66 overview, view facing downstream/east-northeast.



Photograph B49. Freshwater seep (FS01) overview, facing northwest.



Photograph B50. FS01 overview, view facing southeast.



Photograph B51. FS01 overview, facing southeast.



Photograph B52. Wetland determination sampling plot 01 (SP01) within FP01.



Photograph B53. SP01 within FP01, view facing north–northeast.



Photograph B54. SP02 within FP01, view facing west.



Photograph B55. SP03, examined within topographic depression determined to exclude aquatic resources.



Photograph B56. SP03 overview, facing northeast.