



Photograph C. Looking southwesterly into Neighborhood 5 from the intersection of Country Club Drive and Mt. Whitney Road.



Photograph D. On-site pond in Neighborhood 5.

On-site Visual Elements

VALIANO

Figure 2.1-3b



Photograph E. On-site residences in Neighborhood 5.



Photograph F. Looking northeast over the equestrian facility to an off-site hill with residences.

On-site Visual Elements

VALIANO

Figure 2.1-3c



Photograph G. Looking westerly from southeast corner of the Project site.



Photograph H. Looking southwest from private road south of Neighborhood 5.

On-site Visual Elements

VALIANO

Figure 2.1-3d



Photographs I and J. On-site dilapidated barn and existing well tank in southeastern parcel.



Photographs K and L. On-site barns associated with equestrian center in southeastern parcel.

On-site Visual Elements

VALIANO

Figure 2.1-3e