













	⚠ DANGER HIGH VOLTAGE SOLAR DC Contact or disconnecting cables will cause electric shock, burn, arcing or electrocution. Before unplugging cables: ⇒ Move CPV System out of focus. ⇒ Turn off DC switch.			⚠ WARNING HOT SURFACES Contact may cause burn. ⇒ Do NOT touch back of CPV Modules. ⇒ Wear gloves when touching CPV System components.	
	⚠ DANGER HAZARDOUS VOLTAGE Contact will cause electric shock or burn. Before servicing: ⇒ Lock Out, Tag Out (LO/TO) CPV System AC supply power.			⚠ WARNING RISK OF EYE INJURY Highly concentrated light ⇒ Do NOT look directly into the CPV Module from the back side.	
	⚠ WARNING CRUSH HAZARD FROM MOVING PARTS CPV System will be in constant motion while in operation. ⇒ Stay clear of moving mechanism. ⇒ Wear proper Personal Protective Equipment.			⚠ WARNING CRUSH HAZARD FROM MOVING PARTS CPV System will be in constant motion while in operation. ⇒ Stay clear of moving mechanism. ⇒ Wear proper Personal Protective Equipment.	



