



## Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 27. Well 6B Recovery Analysis, Well 6A/6B 72 Hour Constant Rate Test




## Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 28. Well 8 72 Hour Constant Rate Test Water Level Drawdown




## Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 29. Well 8 72 Hour Constant Rate Test Log Water Level Drawdown




# Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 30. Well 8 Cooper-Jacob Straight Line Test  
Well 8 72 Hour Constant Rate Test**



# Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 31. Well 8a Cooper-Jacob Straight Line Test  
Well 8 72 Hour Constant Rate Test**



## Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 32. Well 8 Recovery Analysis,  
Well 8 72 Hour Constant Rate Test**

