


Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 19. Well 8a Water Level Data




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 20. Well 9 Water Level Data




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 21. Old Agricultural Well Water Level Data




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 22. Well 6B Drawdown, Well 6B 12 Hour Step Test




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 23. Well 6B Drawdown, Well 6A/6B 72 Hour Constant Rate Test




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 24. Well 6B Log Drawdown, Well 6A/6B 72 Hour Constant Rate Test




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 25. Well 6B Cooper-Jacob Straight Line Test,
Well 6A/6B 72 Hour Constant Rate Test**




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 26. Well 6 Cooper-Jacob Straight Line Test
Well 6A/6B 72 Hour Constant Rate Test**




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 27. Well 6B Recovery Analysis, Well 6A/6B 72 Hour Constant Rate Test




Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK

Groundwater Resources Investigation Report Rugged Solar Farm Project

Figure 28. Well 8 72 Hour Constant Rate Test Water Level Drawdown



Groundwater Resources Investigation Report Rugged Solar Farm Project

INTENTIONALLY LEFT BLANK