


# Groundwater Resources Investigation Report Rugged Solar Farm Project


## Figure 17. Well 6B Water Level Data






# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 19. Well 8a Water Level Data




# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 20. Well 9 Water Level Data




# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 21. Old Agricultural Well Water Level Data




# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 22. Well 6B Drawdown, Well 6B 12 Hour Step Test




# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 23. Well 6B Drawdown, Well 6A/6B 72 Hour Constant Rate Test




# Groundwater Resources Investigation Report Rugged Solar Farm Project

## Figure 24. Well 6B Log Drawdown, Well 6A/6B 72 Hour Constant Rate Test



# Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 25. Well 6B Cooper-Jacob Straight Line Test,  
Well 6A/6B 72 Hour Constant Rate Test**



# Groundwater Resources Investigation Report Rugged Solar Farm Project

**Figure 26. Well 6 Cooper-Jacob Straight Line Test  
Well 6A/6B 72 Hour Constant Rate Test**

